To The Chairman Kamarhati Municipality 1, M. M. Feeder Road, 24-Paraganas (North), West Bengal -700056

Date: 03 May 2024

Subject: Request for ferrule cleaning for water supply to the residence at 72/6 D. D. Mondal Ghat Road, Dakshineswar

Sir,

I reside at 72/6, D D Mondal Ghat Road, Dakshineswar, in Ward No 12. I want to inform you that the water flow has been relatively poor in the municipal water pipe supplying water to my house for several months and is getting progressively worse every month, probably due to some blockage at the municipal ferrule supplying water to my residence. It is challenging for my family of four to sustain daily water requirements with such a poor water flow.

I implore you to take the necessary action to send municipality-appointed plumbers to clean the municipal ferrule near my residence to improve the water flow to my residence.

Yours sincerely,

Japati Das

Tapati Das 72/6, D. D. Mondal Ghat Road, Dakshineswar 24-Paraganas (North), West Bengal -700076